

Kinetix 3 Component Servo Drive, Firmware Revision 2.22

Catalog Numbers 2071-AP0, 2071-AP1, 2071-AP2, 2071-AP4, 2071-AP8, 2071-A10, 2071-A15

Topic	Page
Enhancements	1
Enhancements with Revision 2.21	1
Corrected Anomalies	2
Corrected Anomalies with Revision 2.10	2
Corrected Anomalies with Revision 2.20	2
Corrected Anomalies with Revision 2.21	2
Corrected Anomalies with Revision 2.22	2
Additional Resources	2

About This Publication

These release notes provide hardware and software enhancements, anomalies, and other usage considerations for the Kinetix® 3 Component Servo Drive.

Enhancements

This section describes the new and updated firmware features provided in this revision.

Table 1 - Enhancements with Revision 2.21

Enhancement	Description
Increased Pairing	Eliminated CAP warning to allow more flexibility in pairing Kinetix 3 drives with TL-Series™ and Bulletin TLY motors.

Corrected Anomalies

This section describes corrected anomalies associated with these revisions.

Table 2 - Corrected Anomalies with Revision 2.10

Corrected Anomaly	Description
Serial Communication	CORRECTED: Serial communication port configuration failure.

Table 3 - Corrected Anomalies with Revision 2.20

Corrected Anomaly	Description
Home to Present Position	CORRECTED: When the homing to Present Position was performed repeatedly, Home Search Failed fault (E.12) occurred. This anomaly was limited to Home to present position Homing method, and did not impact on the other homing method.

Table 4 - Corrected Anomalies with Revision 2.21

Corrected Anomaly	Description
Index 0 Not Occurring	CORRECTED: Home movement in place of Index 0 movement occurred when stop indexing signal was activated and motor was stopped after completing move to target index position.

Table 5 - Corrected Anomalies with Revision 2.22

Corrected Anomaly	Description
TLY-A130P Motor Error	CORRECTED: Catalog number TLY-A130P motor with absolute encoder and no battery backup was giving E30 error during initial powerup.

Additional Resources

These documents contain additional information concerning related products from Rockwell Automation.

Resource	Description
Industrial Automation Wiring and Grounding Guidelines, publication 1770-4.1	Provides general guidelines for installing a Rockwell Automation industrial system.
Product Certifications website, http://www.ab.com	Provides declarations of conformity, certificates, and other certification details.

You can view or download publications at <http://www.rockwellautomation.com/literature/>. To order paper copies of technical documentation, contact your local Allen-Bradley® distributor or Rockwell Automation sales representative.

Allen-Bradley, Kinetix, Rockwell Software, and Rockwell Automation are trademarks of Rockwell Automation, Inc.

Trademarks not belonging to Rockwell Automation are property of their respective companies.

www.rockwellautomation.com

Power, Control and Information Solutions Headquarters

Americas: Rockwell Automation, 1201 South Second Street, Milwaukee, WI 53204-2496 USA, Tel: (1) 414.382.2000, Fax: (1) 414.382.4444

Europe/Middle East/Africa: Rockwell Automation NV, Pegasus Park, De Kleetlaan 12a, 1831 Diegem, Belgium, Tel: (32) 2 663 0600, Fax: (32) 2 663 0640

Asia Pacific: Rockwell Automation, Level 14, Core F, Cyberport 3, 100 Cyberport Road, Hong Kong, Tel: (852) 2887 4788, Fax: (852) 2508 1846

Publication 2071-RN001A-EN-P - October 2011