



## 8 Axis SERCOS interface™ Module Firmware Release v1.19

Cat. No. 1756-M08SE

### Introduction

This release note corresponds to revision 1.19 of the 8 Axis SERCOS interface™ Module. To use this firmware version, update your system as follows:

| <b>Update this software or firmware</b> | <b>To this revision only</b> |
|---|------------------------------|
| Logix5553 Controller                    | 5.5                          |
| Logix5550 Controller                    | 5.5                          |
| RSLogix 5000 Software                   | 5.02                         |

### Enhancements

This revision includes the following enhancement:

- Initial firmware release

**Allen-Bradley Drives**

## Restrictions

- When associating a particular 1394 Drive Axis module with the 8 Axis SERCOS interface™ module using RSLogix5000, make sure that the Drive Axis Module selected matches the actual hardware in use.
- If the SERCOS interface™ network faults, the 8 Axis SERCOS interface™ may hang in network Phase 2: SERCOS Communication Phase LED Alternating RED/GREEN light. If this occurs, reset to the module, power cycle the chassis, or remove and re-insert the 8 Axis SERCOS interface™.

---

### Reach us now at [www.rockwellautomation.com](http://www.rockwellautomation.com)

Wherever you need us, Rockwell Automation brings together leading brands in industrial automation including Allen-Bradley controls, Reliance Electric power transmission products, Dodge mechanical power transmission components, and Rockwell Software. Rockwell Automation's unique, flexible approach to helping customers achieve a competitive advantage is supported by thousands of authorized partners, distributors and system integrators around the world.

**Americas Headquarters**, 1201 South Second Street, Milwaukee, WI 53201-2496, USA, Tel: (1) 414 382-2000, Fax: (1) 414-382-4444  
**European Headquarters SA/NV**, Boulevard du Souverain 36, 1170 Brussels, Belgium, Tel: (32) 2 663 0600, Fax: (32) 2 663 0640  
**Asia Pacific Headquarters**, 27/F Citicorp Centre, 18 Whitfield Road, Causeway Bay, Hong Kong, Tel: (852) 2887 4788, Fax: (852) 2508 1846

Publication 1756-RN575A-EN-P - February 2001



PN 957491-94

© 2001 Rockwell International Corporation. Printed in the U.S.A.