

1313 Parts List

Part No.	Description
416454	Non-Reversing Motor Contactor Assembly (2 NO - 2 NC Contacts)
416455	Reversing Motor Contactor Assembly (3 NO - 3 NC Contacts)
455886	Silicon Rectifier Encapsulated Bridge Assembly
16691-N	Contact Protector (resistor-capacitor combination)
233345	Overload Relay Spindle (only)
815-BOV4	Manual Reset Overload Relay Assembly
1492-F1	Terminal Blocks (300V. max.)
455877	Full Wave Module Assembly
300891	Silicon Controlled Rectifier "1SCR" only
455599	Printed Circuit Card Assembly (only)
391083	Fuse "1FU" (only) 30A - 130V1
40144-002-51	Max., Min., Speed, & Timed Accel Pot Assembly
JA1N032S502UA	Speed Pot "27R" (only) 5K - 2W
JA1N032S252UA	Speed Pot "28R" (only) 2.5K - 2W
EB-5125	Fixed Resistor "26R" (only) 5.1K - .5W
J96807	Accel. Pot "32R" (only) 20M - 2W
130556	Dropping Resistor "23R" (only) 3K - .25W
395248	Dynamic Brake Resistor "1DBR" (only) 5 ohm - 100W
332425	Anti-Plugging Relay Assembly (used w/reversing only)