

**1326DP Motor Parts
DC Servomotor for use with the 1388 Drive**

<u>Catalog Number</u>	<u>Part Number</u>	<u>Description</u>
<i>Motor Brushes:</i> (one brush per part number, 4 to 16 brushes are used on each motor)		
*****	111875	DP-A & DP-I Motors
*****	111876	DP-C, DP-E, DP-S Motors
*****	111879	DP-U Motors
*****	111880	DP-W & DP-X Motors
*****	111878	DP-M Motors
*****	111881	DP-P Motors

<i>Tachometer Brushes:</i> (one brush per part number, typically 4 required)		
*****	111882	All 1326DP motors

Note: All other parts for the 1326DP motors can be obtained by calling Peerless-Winsmith at (330) 399-3651.

Note: All other parts for the 1326DP motors can be obtained by calling Peerless-Winsmith at (330) 399-3651.