



Firmware Release Notes

ControlLogix Drive Module

(Cat. No. 1756-DMF30)

These release notes correspond to major revision 1, minor revision 09 of the ControlLogix Drive Module firmware. Use this firmware release with:

Software Product:	Compatible Version:
RSLogix 5000 programming software	8.02.00
RSLink software	2.30
RSNetWorx for ControlNet software	3.00
DriveExecutive programming software	1.01

Restrictions

SynchLink communication is not available. It will be available in a future version. Parameters and configuration windows, related to SynchLink, will be visible but not functional.

The SynchLink documentation in the *Drive Module System User Manual*, publication 1756-UM522A-EN-P, does not apply at this time.

PMI Communication Failures During Power Up - The Drive Module may experience PMI communication faults, after power to the Drive Module or PMI chassis is cycled. Clear these faults by doing one of the following:

- Cycling power on the PMI chassis.
- Clearing faults in DriveExecutive programming software - In the “Fault Alarm Information” window, click the “Clear Faults” button; or Select “Faults and Alarms” from the Drive Menu, then click “Clear Fault”.
- Clearing faults in RSLogix programming software - Manually set bit 14[ClearFault] of the Logic Command word while on the “Monitor Tags” tab of the “Controller Tags” window; or program ladder logic to set and reset this bit.

www.rockwellautomation.com

Corporate Headquarters

Rockwell Automation, 777 East Wisconsin Avenue, Suite 1400, Milwaukee, WI, 53202-5302 USA, Tel: (1) 414.212.5200, Fax: (1) 414.212.5201

Headquarters for Allen-Bradley Products, Rockwell Software Products and Global Manufacturing Solutions

Americas: Rockwell Automation, 1201 South Second Street, Milwaukee, WI 53204-2496 USA, Tel: (1) 414.382.2000, Fax: (1) 414.382.4444

Europe: Rockwell Automation SA/NV, Vorstlaan/Boulevard du Souverain 36-BP 3A/B, 1170 Brussels, Belgium, Tel: (32) 2 663 0600, Fax: (32) 2 663 0640

Asia Pacific: Rockwell Automation, 27/F Citicorp Centre, 18 Whitfield Road, Causeway Bay, Hong Kong, Tel: (852) 2887 4788, Fax: (852) 2508 1846

Headquarters for Dodge and Reliance Electric Products

Americas: Rockwell Automation, 6040 Ponders Court, Greenville, SC 29615-4617 USA, Tel: (1) 864.297.4800, Fax: (1) 864.281.2433

Europe: Rockwell Automation, Brühlstraße 22, D-74834 Eitzal-Dallau, Germany, Tel: (49) 6261 9410, Fax: (49) 6261 1774

Asia Pacific: Rockwell Automation, 55 Newton Road, #11-01/02 Revenue House, Singapore 307987, Tel: (65) 351 6723, Fax: (65) 355 1733

U.S. Allen-Bradley Drives Technical Support

Tel: (1) 262.512.8176, Fax: (1) 262.512.2222, Email: support@drives.ra.rockwell.com, Online: www.ab.com/support/abdrives