



FlexLogix Controller System

Catalog Number 1794-L34/B

This release note should be used with the 1794-L34/B controller.

Use Correct Firmware Revision

The 1794-L34/B controller **must** use the FlexLogix controller firmware major revision 11 minor revision 22 (i.e. 11.22) or greater.

The 1794-L33 or 1794-L34/A controllers using major revision 11, can use minor revision 21 or greater (i.e. 11.21 or greater).

Obtaining Firmware

For more information on upgrading your controller's firmware, see page 19 of the FlexLogix System Installation Instructions, publication 1794-IN002. The installation instructions also shipped with your controller.

www.rockwellautomation.com

Corporate Headquarters

Rockwell Automation, 777 East Wisconsin Avenue, Suite 1400, Milwaukee, WI, 53202-5302 USA, Tel: (1) 414.212.5200, Fax: (1) 414.212.5201

Headquarters for Allen-Bradley Products, Rockwell Software Products and Global Manufacturing Solutions

Americas: Rockwell Automation, 1201 South Second Street, Milwaukee, WI 53204-2496 USA, Tel: (1) 414.382.2000, Fax: (1) 414.382.4444

Europe: Rockwell Automation SA/NV, Vorstlaan/Boulevard du Souverain 36-BP 3A/B, 1170 Brussels, Belgium, Tel: (32) 2 663 0600, Fax: (32) 2 663 0640

Asia Pacific: Rockwell Automation, 27/F Citicorp Centre, 18 Whitfield Road, Causeway Bay, Hong Kong, Tel: (852) 2887 4788, Fax: (852) 2508 1846

Headquarters for Dodge and Reliance Electric Products

Americas: Rockwell Automation, 6040 Ponders Court, Greenville, SC 29615-4617 USA, Tel: (1) 864.297.4800, Fax: (1) 864.281.2433

Europe: Rockwell Automation, Brühlstraße 22, D-74834 Elztal-Dallau, Germany, Tel: (49) 6261 9410, Fax: (49) 6261 17741

Asia Pacific: Rockwell Automation, 55 Newton Road, #11-01/02 Revenue House, Singapore 307967, Tel: (65) 351 6723, Fax: (65) 355 1733

Publication 1794-RN002A-EN-P - November 2002

PN 957726-42